



W292S4498 Hillside Rd. Waukesha, WI 53189

262-896-6780 Fax 262-896-6756

[www.midwestindustriesinc.com](http://www.midwestindustriesinc.com)

## **MI-MP5-OR Installation Instructions**

**(Failure to read and follow these instructions will void your warranty)**

1. Please make sure your firearm is unloaded and pointed in a safe direction.
2. Set the mount on top of your rifle or pistol with the laser engraving on the ejection port side .
3. Install the provided clamps one at a time. The beveled edge goes towards the gun with the 45-degree angle going towards the floor. Install all four and use the provided blue thread lock. Finger tighten only.
4. Torque the four socket heads to 20-inch pounds.



W292S4498 Hillside Rd. Waukesha, WI 53189

262-896-6780 Fax 262-896-6756

[www.midwestindustriesinc.com](http://www.midwestindustriesinc.com)

## **MI-MP5-OR Installation Instructions**

**(Failure to read and follow these instructions will void your warranty)**

1. Please make sure your firearm is unloaded and pointed in a safe direction.
2. Set the mount on top of your rifle or pistol with the laser engraving on the ejection port side .
3. Install the provided clamps one at a time. The beveled edge goes towards the gun with the 45-degree angle going towards the floor. Install all four and use the provided blue thread lock. Finger tighten only.
4. Torque the four socket heads to 20-inch pounds.