



Stock Tube Adaptor Instructions

MI-STAP, MI-STAP-LWS, MI-STAP-PB, MI-ALPHA-FBS, MI-ALPHA-M4BS

1. Please make sure the firearm is unloaded and pointed in a safe direction.
2. Repeat step one.
3. Remove the cross bolt on the mounting block.
4. Slide onto the receiver rail.
5. Re-install cross bolt
6. Torque cross bolt to 40inch pounds or until mounting block does not slide. Do not exceed 60inch pounds.

For MI-STAP-BT

1. Follow same steps above to attach side folder to firearm
2. Screw buffer tube onto back of side folder
3. Use set screw to secure buffer tube to side folder adaptor

W292S4498 Hill Side Rd. Waukesha, WI 53189
262-896-6780 Fax 262-896-6756
www.midwestindustriesinc.com



Stock Tube Adaptor Instructions

MI-STAP, MI-STAP-LWS, MI-STAP-PB, MI-ALPHA-FBS, MI-ALPHA-M4BS

1. Please make sure the firearm is unloaded and pointed in a safe direction.
2. Repeat step one.
3. Remove the cross bolt on the mounting block.
4. Slide onto the receiver rail.
5. Re-install cross bolt
6. Torque cross bolt to 40inch pounds or until mounting block does not slide. Do not exceed 60inch pounds.

For MI-STAP-BT

1. Follow same steps above to attach side folder to firearm
2. Screw buffer tube onto back of side folder
3. Use set screw to secure buffer tube to side folder adaptor

W292S4498 Hill Side Rd. Waukesha, WI 53189
262-896-6780 Fax 262-896-6756
www.midwestindustriesinc.com